

R44

Page 1 of 1

SERVICE LETTER SL-35

DATE: 18 March 2008

TO: R44 II Owners, Operators, and Service Centers

SUBJECT: Servo Plugs

BACKGROUND: The U.S. FAA has issued Emergency AD 2008-06-51 in response to reports of engine power loss due to loose fuel injection servo plugs. R44 II helicopters are equipped with RSA-10 series fuel injection servos, also known as fuel control units, which are affected by the AD.

COMPLIANCE PROCEDURE:

Prior to further flight, follow AD 2008-06-51 instructions. The AD may be downloaded from: www.faa.gov/aircraft/safety/alerts.