



## Pricing for R44 2200-Hour Maintenance & Inspection Performed at RHC

Below pricing for R44 2200-Hour Maintenance and Inspection performed at RHC effective **9 April 2024**. Base price is for an airworthy R44 properly maintained, undamaged and without excessive corrosion. Additional maintenance and/or inspections will be required for helicopters with optional equipment, 4400-hours, or if discrepancies are found during helicopter disassembly and evaluation.

Base price includes the 2200-Hour engine overhaul performed by RHC or Lycoming and the following fatigue life-limited parts, parts with a recommended time between overhaul (TBO), and parts with a recommended replacement of 2200-hours:

### Exchange Components

C006 MR Gearbox  
 C017 Swashplate  
 C018 Clutch  
 C021 TR Gearbox  
 C051 Actuator  
 D174 Fanwheel  
 Engine

### New Parts

A120 Bellcrank	C169 Muffler
A190 Drive V-Belts	C170 Sheave
C008 TR Assembly	C258 Pitch Links
C016 MR Blades	C274 Windshields
C020 Upper Frame	C667 Skid Shoes
C027 Cooling Panels	C947 & A947 Flex Plates
C121-17 P/P Tube	D079 TR Guard
C005 MR Hub	D224 TR Driveshaft
C158 MR Spindles	C031 TR Pitch Control
C159 Pitch Bearings	C007-5 Fan Shaft & Bearing
Shell, Fuel Tanks	Various small parts & hardware

**Base Price R44 Raven I/Cadet (2400-Hours) (does not include upgrades) ..... \$288,000.00 + upgrades**

**Base Price R44 Raven II (does not include upgrades) ..... \$310,000.00 + upgrades**

<u>Applicability</u>	<u>Description</u>	<u>Price</u>
Required thru S/N 0663	Hydraulic Flight Controls (includes pistol grip)	\$63,000.00
Required	KI-163 Full-Flow Oil Filter	\$620.00
Required	KI-218 Full Throttle Caution Light (see attached for pricing)	
Optional	D575 Pneumatic Front Door Opener	\$10,840.00
Required	C034-5 Pop-Out Float Overhaul (includes new floats, covers & cylinder exchange)	\$35,000.00
Required	C034-4 Fixed Float Overhaul (includes new floats)	\$34,000.00
Required	KI-196-1 or -2 Fuel Bladder Tanks	\$14,500.00
Required	Camshaft & Valve Train Parts (flat)	\$6,207.00
Required	Camshaft & Valve Train Parts (roller)	\$14,154.00
<b>Required</b>	<b>KI-275 Cockpit Camera</b>	<b>\$3,800.00</b>
Optional	G084-3 Impact Resistant Windshields	\$18,850.00
Optional, 10001 & subsequent	Air Conditioning	\$25,400.00

### Base price also includes:

Complete refurbishing of helicopter interior including new seats (velour), carpet (charcoal only) and headliner. Additional cost for leather seats is \$1,820.00/Cadet \$920.00. Complete repaint of helicopter exterior including white base with standard trim color (other options available at additional costs). Crating \$8,000.00. Production-equivalent minor upgrades and up-to-date Service Bulletin compliance. The RHC Limited Parts Warranty covers parts replaced, repaired and/or overhauled for a period of 1-year or 1000-hours, whichever event occurs first; provided the part has been subjected to normal use and service.

Specifications and prices are subject to change without prior notice. Prices net RHC factory, no Dealer/Service Center discounts apply. For further information, contact [cs1@robinsonheli.com](mailto:cs1@robinsonheli.com).