



Pricing for R66 2200-Hour Maintenance and Inspection Performed at RHC

Below pricing for R66 2000-Hour Maintenance and Inspection performed at RHC effective **9 April 2024**. Base price is for an airworthy R66 properly maintained, undamaged and without excessive corrosion. Additional maintenance and/or inspections will be required for helicopters with optional equipment, 4000-hours, or if discrepancies are found during helicopter disassembly and evaluation.

Base price includes RR300 engine 2000-Hour Preventative Maintenance Inspection (PMI) performed by a Rolls-Royce Authorized Maintenance, Repair & Overhaul Center (AMROC) and the following fatigue life-limited parts, parts with a recommended time between overhaul (TBO), and parts with a recommended replacement time of 2000-hours:

Exchange Components

- C005 MR Blade & Spindle Assembly (set)
- C021 TR Gearbox
- F001 MR Gearbox Sub-Assembly
Includes:
 - C017 Swashplate
 - D211 Hydraulic Reservoir
 - D212 Hydraulic Servos
 - D500 Pump Assemblies
 - F006 MR Gearbox
 - G201 Servo Support Frame (new)
 - F018 Clutch
 - F649 Engine Oil Cooler

New Parts

- A120 Bellcrank
- A522 Control Cables
- A947 Flex Plates
- B345 TR Pitch Links
- C005 MR Hub
- C008 TR Assembly
- C522 Control Cables
- C947 Flex Plates
- D224 TR Drive Shaft
- F020 Upper Frame
- F173 Exhaust Support Struts
- F235 Upper Frame Struts
- F252 Upper Frame Strut
- F642 Engine Shaft Weldment
- C031 TR Pitch Control
- F792 Dual Tachometer
- C649 Oil Cooler
- Various small parts & hardware

Base Price (does not include upgrades) \$398,000.00 + upgrades

Base price also includes:

- Complete refurbishing of helicopter interior including new seats (leather), carpet (charcoal only) and headliner.
- Complete repaint of helicopter exterior including white base with standard trim color (other options available at additional costs). Crating \$9,000.00.
- Production-equivalent minor upgrades and up-to-date Service Bulletin compliance.

Optional equipment:

- DER-approved repairs.
- C034-4 Fixed float overhaul (includes new floats) \$34,000.00.
- C034-5 Pop-out float overhaul (includes new floats, covers & cylinder exchange) \$35,000.00.
- RR300 4th stage wheel replacement (SB A-72-024). Determined by vendor.
- G084-1 Impact resistant windshields \$19,150.00.

Required

- KI-6602-1 4000-Hour Tailcone & Horizontal Stabilizer Kit \$19,100.00
- KI-6602-2 2000-Hour Tailcone & Horizontal Stabilizer Kit \$14,500.00
- **KI-275 Cockpit Camera \$3,800.00**



The RHC Limited Parts Warranty covers parts replaced, repaired and/or overhauled for a period of 1-year or 1000-hours, whichever event occurs first; provided, the part has been subjected to normal use and service. The RR300 Rolls-Royce engine warranty is determined by the independent repair/overhaul facility.

Specifications and prices are subject to change without prior notice. Prices net RHC factory, no Dealer/Service Center discounts apply. For further information, contact cs1@robinsonheli.com.