

R22 DEALER AND SERVICE CENTER REQUIRED EQUIPMENT

Required Spares:

KI-24	R22 Minimum Spares Kit (includes Maintenance Manual, Parts Catalog and 1-year subscription)	\$6,600.00
-------	---	-------------------

Required Tools:

KI-115	Syringe and Probe for A184 Bearing	\$13.00
MT050-1	Main Rotor Rigging Tool	\$67.00
MT050-2	Tail Rotor Rigging Tool	\$56.00
MT053-1	MRGB Drain Valve Tool	\$106.00
MT054-1	MRGB Drain Valve Tool - Quick Disconnect	\$107.00
MT091-1	Engine Ring Gear Holding Tool	\$94.25
MT092-1	Fan Puller	\$176.00
MT121-1	Bracket - Magnetic Pickup	\$92.00
MT122-1	Main Rotor Hub Bolt Stretch Micrometer	\$959.00
MT133-1	Tool Assembly - Parallel Valve	\$401.00
MT133-9	Adapter Assembly	\$92.25
MT147-1	Main Rotor Blade Spindle Air Bleed Tools	\$276.00
MT201-1	Pressing Fixture for .250 diameter Bore Spherical Bearing	\$226.00
MT260-6	TRDS Run Out Attachments	\$129.00
MT295-1	TRGB Output Shaft Seal Replacement Tool	\$284.00
MT331-4	Sheave Alignment Bar	\$64.50
MT352-1	Main Rotor Blade Trim Tab Gauge	\$345.00
MT354-1	Teeter Moment Tool	\$243.00
MT357-1	0.125 inch diameter Cobalt Steel Drill	\$4.00
MT357-2	0.375 inch diameter Reamer	\$89.00
MT358-1	0.75 inch diameter Spot Facing Tool	\$144.00
MT359-1	Spring Scale	\$222.00
MT376-1	Rigging Block	\$443.00
MT526-1	Bender Assembly - Cyclic Trim Tab, MR Blade	\$308.00
KI-68	Model 2000 Balancer System (or equivalent)**	\$9,474.00

TOTAL TOOLS PRICE:

\$14,415.00

Recommended Tools:

MT016-1	Engine Hoist	\$303.00
MT068-1	Horizontal Stabilizer Rigging Tool	\$70.25
MT173-5	Torque Wrench Extension - Fan Shaft Nut (for use when 400 ft-lb capacity torque wrench is unavailable)	\$343.00
MT294-1	Collective Spring Retainer	\$113.00
MT303-1	Clutch Bearing Removal and Installation Tool	\$512.00
MT303-3	Clutch Bearing Removal and Installation Tool	\$1,072.00

TOTAL RECOMMENDED TOOLS PRICE:

\$2,413.25

**No discount.

Prices are subject to change without notice.

January 15, 2008